

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

Facility Audited: Bald Mountain Mine, Nevada, USA

Date: January 8, 2008

Lead Auditor and Technical Expert Credentials

Lead Auditor: Scott H. Miller, P.G., CEA

Golder Associates Inc.

44 Union Blvd., Suite 300

Lakewood, CO 80228

Certifying Organization: National Registry of Environmental
Professionals (NREP)

Address: PO Box 2099, Glenview, IL 60025

Auditor Certification Number: 9752

Telephone Number: (303) 980-0540

Telephone Number.: (847) 724-6631

Web Site Address: www.nrep.org

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
2007	Cortez Gold Mines - Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
2007	Laguna Norte Mine - Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Libertad, Peru
2007	Ruby Hill Mine - Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
2007	Pierina Mine - Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Ancash, Peru
2007	Goldstrike Mine - Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
2007	Twin Creeks Mine – Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
2007	Lone Tree Mine – Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
2006	Glamis Marigold Mine – Lead Auditor for the verification audit for compliance with the ICMC. Audit followed the ICMI verification protocols for Gold Mining Operations.	Nevada, USA
2006	Cyanco and TransWood Facilities – Lead Auditor for the verification audits for compliance with the ICMC. Audits followed the ICMI verification protocols for Cyanide Manufacturers and Transporters.	Nevada, USA
2006	Confidential gold cyanide heap leach facility – Lead Auditor for Gap analysis and verification audit for compliance with the ICMC. Audit followed ICMI verification protocol and included development of detailed audit report and action plan.	Nevada, USA

Year	Type of Facility, Type of Audit Led	Country & State/Province
2002-2006	United Park City Mines Company - Historic mining and milling complex including two CERCLIS sites and 14 mine/mill sites; lead auditor for comprehensive environmental compliance audit and liability cost assessment. Original audit and liability assessment report delivered December 2002, since then have completed quarterly compliance audits including interviews, review of new documents and remediation progress, site visits and reporting.	Utah, USA
2005	Confidential gold cyanide heap leach facility - Environmental compliance audit and due diligence for stock purchase of company, including interviews, record review, and permit compliance. Compliance issues identified and corrective action plans and cost estimates developed.	Nevada, USA
1997-2006	Climax Mine - Remediated mill tailings impoundment; Comprehensive 3 rd -party environmental compliance audit during and post-remediation for conversion of impoundment for water storage reservoir on Eagle River. Ongoing annual audits of facility include interviews, document review, site visits, water quality compliance verification sampling and reporting.	Colorado, USA
2001	Ruby Hill Mine - Gold cyanide heap leach facility; Compliance audit of mine closure plan including cyanide facility closure and cost estimate.	Nevada, USA
1999	ZCCM - Copper-cobalt mine and mill complex; Compliance audit of facility against World Bank compliance criteria.	Konkola, Zambia

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Scott H. Miller, CEA	16	Mining Environmental Consultant	Since 1991, Mr. Miller has provided environmental consulting services for the mining industry. Approximately 75% of his time has been spent with gold operations including geologic and geochemical site characterizations, new mine operating plans, mine permitting, compliance auditing, remediation plans, water management plans, cyanide facility closure plans, closure cost assessment, and water quality compliance management.

