

### Auditor Credentials Form

**Facility Audited: Harmony Target Gold Plant, South Africa**

**Date: 8<sup>th</sup> – 12<sup>th</sup> February 2010**

**Lead Auditor Credentials**

Lead Auditor: Arend Hoogervorst  
 Eagle Environmental  
 Private Bag X06  
 KLOOF 3640, South Africa

Tel: - +27 31 7670244  
 Fax: - +27 31 7670295  
 Email: - [arend@eagleenv.co.za](mailto:arend@eagleenv.co.za)

Certifying Organization: Name: RABQSA  
 Telephone Number: - +61 2 4728 4600  
 Address: P O Box 347, Penrith BC, NSW 2751, Australia  
 Web Site Address: - [www.rabqsa.com](http://www.rabqsa.com)

Auditor Certification Number: 12529

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
1991 to 2007 – 111 audits (Audit logs held by RABQSA & ICMI)	Chemicals, manufacturing, oil and gas, mining (gold, coal, chrome), foods, and heavy industry sectors. EMS, Compliance, Environmental Due Diligence, HSEC, SHE audits. Lead Auditor in 81 audits.	South Africa, Botswana, Mozambique, Mali, Namibia, Ghana
2006	<b>ICMI Cyanide Code Compliance Audits: Lead Auditor</b> *Sasol Polymers Cyanide Plants 1 & 2 and Storage Areas (Production) *Sasol SiLog (Transportation)	South Africa South Africa
2007	<b>ICMI Cyanide Code Compliance Audits: Lead Auditor</b> *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold Plant *AngloGold Ashanti Kopanang Gold Plant *AngloGold Ashanti Savuka Gold Plant *AngloGold Ashanti Mponeng Gold Plant	South Africa South Africa South Africa South Africa South Africa South Africa
2007	<b>ICMI Cyanide Code Gap Analyses: Lead Auditor</b> *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine *Goldfields South Deep Gold Mine *Goldfields Beatrix 1 Gold Mine *Goldfields Beatrix 2 Gold Mine *Goldfields Driefontein No 1 Gold Mine	Ghana Ghana South Africa South Africa South Africa

2008	<ul style="list-style-type: none"> <li>*Goldfields Kloof No 1 Gold Mine</li> <li>*Goldfields Kloof No 2 Gold Mine</li> <li>*Goldfields Driefontein No 2Gold Mine</li> <li>*Goldfields Driefontein No 3 Gold Mine</li> <li>*Goldfields St Ives Gold Mine</li> <li>*Goldfields Agnew Gold Mine</li> <li>* Harmony No 1 Gold Plant</li> <li>*AngloGold Ashanti Africa – Morila Gold Mine</li> <li>* AngloGold Ashanti Africa – Sadiola &amp; Yatela Gold Mines</li> </ul> <p><b>ICMI Cyanide Code Compliance Audits: Lead Auditor</b></p> <ul style="list-style-type: none"> <li>*Goldfields Tarkwa Gold Mine</li> <li>*Goldfields Abusso Damang Mine</li> <li>*Vehrad Transport &amp; Haulage</li> <li>* Goldfields South Deep Gold Mine</li> <li>* Goldfields Beatrix Gold Mine</li> <li>*Goldfields Driefontein Gold Mine</li> <li>* Goldfields St Ives Gold Mine</li> <li>* Goldfields Agnew Gold Mine</li> <li>* Goldfields Kloof Gold Mine</li> <li>* AngloGold Ashanti Africa – Siguiri Gold Mine</li> <li>* AngloGold Ashanti Africa – Yatela Gold Mine</li> </ul>	<p>South Africa South Africa South Africa South Africa Australia Australia South Africa Mali Mali</p> <p>Ghana Ghana Ghana South Africa South Africa South Africa Australia Australia South Africa Guinea Mali</p>
2008	<p><b>ICMI Cyanide Code Gap Analyses: Lead Auditor</b></p> <ul style="list-style-type: none"> <li>*AngloGold Ashanti Africa – Navachab Gold Mine</li> <li>*AngloGold Ashanti Africa – Gaita Gold Mine</li> <li>*Harmony Doornkop Gold Mine</li> <li>*AngloGold Ashanti Africa – Iduapriem Gold Mine</li> <li>*AngloGold Ashanti Africa – Siguiri Gold Mine</li> <li>*Harmony Central Gold Mine</li> <li>*Harmony Kalgold Gold Mine</li> <li>*Harmony Evander Gold Mine</li> <li>*Harmony Target Gold Mine</li> <li>*Harmony Saaiplaas Gold Mine</li> </ul>	<p>Namibia Tanzania South Africa Ghana Guinea South Africa South Africa South Africa South Africa South Africa</p>
2009	<p><b>ICMI Cyanide Code Compliance Audits: Lead Auditor</b></p> <ul style="list-style-type: none"> <li>*Sasol Polymers Cyanide Plants 1 &amp; 2 and Storage Areas (Production)</li> <li>*Sasol SiLog (Transportation)</li> </ul>	<p>South Africa South Africa</p>
2010	<p><b>ICMI Cyanide Code Compliance Audits: Lead Auditor</b></p> <ul style="list-style-type: none"> <li>*Harmony Elandsrand Gold Plant</li> </ul>	<p>South Africa</p>

	*Harmony No 1 Gold Plant	South Africa
--	--------------------------	--------------

### Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience




Auditor	Yrs.	Relevant Position Titles	Types of Operations
Dawie Viljoen	32	2010	<b>ICMI Cyanide Code Compliance Audits: Technical Auditor</b> *Harmony Elandsrand Gold Plant *Harmony No 1 Gold Plant
		2009	<b>ICMI Cyanide Code Compliance Audits: Technical Auditor</b> *Sasol Polymers Cyanide Plants 1 & 2 and Storage Areas (Production) *Sasol SiLog (Transportation)
		2008	<b>ICMI Cyanide Code Compliance Audits: Technical Auditor</b> *Goldfields Tarkwa Gold Mine *Goldfields Abusso Damang Mine * Goldfields South Deep Gold Mine * Goldfields Beatrix 2 Gold Mine * Goldfields Beatrix 1 Gold Mine * Goldfields Driefontein 1 Gold Mine * Goldfields Driefontein 2 Gold Mine * Goldfields Driefontein 3 Gold Mine * Goldfields St Ives Gold Mine * Goldfields Agnew Gold Mine * Goldfields Kloof 1 Gold Mine * Goldfields Kloof 2 Gold Mine
		2008	<b>ICMI Cyanide Code Gap Analyses: Technical Auditor</b> *AngloGold Ashanti Africa – Navachab Gold Mine *AngloGold Ashanti Africa – Gaita Gold Mine *Harmony Doornkop Gold Mine *AngloGold Ashanti Africa – Iduapriem Gold Mine *AngloGold Ashanti Africa – Siguiru Gold Mine *Harmony Central Gold Mine *Harmony Kalgold Gold Mine *Harmony Evander Gold Mine *Harmony Target Gold Mine *Harmony Saaiplaas Gold Mine
		2007	<b>ICMI Cyanide Code Compliance Audits: Technical Auditor</b> *AngloGold Ashanti West Gold Plant *AngloGold Ashanti East Gold Acid Float Plant *AngloGold Ashanti Noligwa Gold

			<ul style="list-style-type: none"> <li>Plant</li> <li>*AngloGold Ashanti Kopanang Gold Plant</li> <li>*AngloGold Ashanti Savuka Gold Plant</li> <li>*AngloGold Ashanti Mponeng Gold Plant</li> </ul>
	2007		<p><b>ICMI Cyanide Code Gap Analyses:</b></p> <p><b>Technical Auditor</b></p> <ul style="list-style-type: none"> <li>*Goldfields Tarkwa Gold Mine</li> <li>*Goldfields Abusso Damang Mine</li> <li>*Goldfields South Deep Gold Mine</li> <li>*Goldfields Beatrix 1 Gold Mine</li> <li>*Goldfields Beatrix 2 Gold Mine</li> <li>*Goldfields Driefontein No 1 Gold Mine</li> <li>*Goldfields Kloof No 1 Gold Mine</li> <li>*Goldfields Kloof No 2 Gold Mine</li> <li>*Goldfields Driefontein No 2 Gold Mine</li> <li>*Goldfields Driefontein No 3 Gold Mine</li> <li>*Goldfields St Ives Gold Mine</li> <li>*Goldfields Agnew Gold Mine</li> <li>*Harmony No 1 Gold Plant</li> <li>*AngloGold Ashanti Africa – Morila Gold Mine</li> <li>*AngloGold Ashanti Africa – Sadiola &amp; Yatela Gold Mines</li> </ul>
	2006		<ul style="list-style-type: none"> <li>*AngloGold Ashanti West Gold Plant</li> <li>*AngloGold Ashanti East Gold Acid Float Plant</li> <li>*AngloGold Ashanti Noligwa Gold Plant</li> <li>*AngloGold Ashanti Kopanang Gold Plant</li> <li>*AngloGold Ashanti Savuka Gold Plant</li> <li>*AngloGold Ashanti Mponeng Gold Plant</li> </ul>
	2000 to 2007		Managing Member Afritech Technical and Management services
	1997 - 2000		Manager: AngloGold Ashanti Metallurgical Technical Services
	1995 - 1997		Metallurgical Manager: Vaal Reefs Exploration and Mining Company
	1990 - 1995		Project Metallurgist: Vaal Reefs Exploration and Mining Company Projects
	1987 – 1990		Plant Manager: Vaal Reef Exploration and Mining Company

	1980- 1985	Production Superintendent Anglo American
	1977 - 1980	Snr Plant Metallurgist – Anglo American

**Statement of No Conflict**

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed,	Name	Signature	Date
Lead Auditor*	Arend Hoogervorst		9/4/10
Notarised/certified			9/4/2010
Technical Auditor	Dawie Viljoen		16/4/2010 <b>ANGELA LOUISE KLYNHANS</b> Manager Unit Trust Division Ewing Trust Company Commissioner of Oaths RSA 28 Old Main Road, Hillcrest, 3610 REF: 9/1/8/2 Hillcrest 07/07/2009

\*The lead auditor's signature must be certified by notarization or equivalent