

INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

Facility Audited: Newmont Ghana Gold Limited, Ahafo Gold Mine, Ghana

Date: March 12th 2008

Lead Auditor Credentials

Lead Auditor: Hugh Wyndham, Bag Ec., MSc. AFAIM
Golder Associates Pty Ltd
124 Pacific Highway, Greenwich
NSW 2065 Australia

Auditor Certification Number: 007058

Certifying Organization: RABQSA
Address: Suite 102, 148 Henry Street
P.O. Box 347
Penrith BC, NSW 2751
Australia

Telephone Number.: +61 2 4728 4600

Web Site Address: www.rabqsa.com

Minimum experience: 3 audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country & State/Province
2000 and 2001	Lead Auditor for environmental management audits that included coverage of hazardous materials management (reagents) and emergency response. The gold recovery process includes cyanide leaching and carbon adsorbtion.	Western Australia
2003	Lead auditor of an environmental and community relations' audit that included assessment of the management of cyanide in gold recovery covering the handling, storage and use of cyanide in process operations (CIP/CIL and heap leach) and the handling, storage and use of other hazardous materials.	Republic of Mali
2003	Lead auditor of an environmental and community relations' audit that included assessment of the management of cyanide in gold recovery covering the handling, storage and use of cyanide in process operations and the handling, storage and use of other hazardous materials.	Republic of Mali
2004	Lead auditor for a pilot audit for the Mining Certification Evaluation Project that covers Environment, Health and Safety, Employee Relations and Community Relations. Process operations include an agitation leaching and CIP circuit.	Western Australia
2001	As a member of an audit team addressing the management of health and safety, environmental, and	Western Australia

Ahafo Gold Mine


Signature of Lead Auditor

March 12 2008

	mine closure aspects at three gold mines in WA. Ore is recovered from underground and open pits operations. Environmental aspects included those associated with the mill operations covering oxide and sulphide circuits, producing doré for offsite refining into gold bullion.	
2001-2007	Sole auditor for certification of gold mine to ISO 14001, four subsequent surveillance assessments, and a re certification assessment. The mine EMS covers the management of cyanide and other hazardous materials and chemical emergency response.	Tanzania
2002-2005	Sole auditor for certification of gold mine to ISO 14001 and four subsequent surveillance assessments and a re-certification assessment. The mine EMS covers the management of cyanide and other hazardous materials and chemical emergency response.	Republic of Ghana
2003-2007	Sole auditor for certification of gold mine to ISO 14001 and four subsequent surveillance assessments and a re-certification assessment. The mine EMS covers the management of cyanide and other hazardous materials and chemical emergency response.	Republic of Ghana
2005-2007	Sole auditor for certification of gold mine to ISO 14001 and two subsequent surveillance assessments. The mine EMS includes the management of cyanide and other hazardous materials and chemical emergency response.	Republic of Guinea
2006-2007	Sole auditor for certification of gold mine to ISO 14001 and a subsequent Surveillance Assessment. The mine EMS includes the management of cyanide and other hazardous materials and chemical emergency response.	Republic of Ghana
2006-2007	Sole auditor for certification gold mine to ISO 14001 and a subsequent Surveillance Assessment. The mine EMS includes the management of cyanide and other hazardous materials and chemical emergency response.	Republic of Mali
2006-2007	Sole auditor for certification of gold mine to ISO 14001 and a subsequent Surveillance Assessment. The mine EMS includes the management of cyanide and other hazardous materials and chemical emergency response.	Republic of Mali
2007	Lead auditor for operations audit of gold mine against the ICMC. Audit team consisted of a Lead Auditor and a Technical Expert.	Republic of Ghana
2007	Sole auditor for certification of gold mine to ISO 14001. The mine EMS includes the management of cyanide and other hazardous materials and chemical emergency response.	Republic of Mali

Cyanide-related Operations Experience



Each auditor must have at least 3 years; at least one auditor must have at least 7 years experience

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Hugh Wyndham Lead Auditor	8	Associate, Lead Environmental Auditor	Environmental auditing services for coal and gold mining industry. Auditing of coal mining operations since 1991 and of gold mining operations since 2000. Auditing of gold mines has covered both Certification of mine environmental management systems to ISO 14001 and broader based environmental audits of mining operations, including the management of reagents and other hazardous materials and of compliance with regulatory and other requirements. Total estimated time spent auditing gold mining operations, including reporting, over the period 2000 to 2007 is approximately 58 weeks.
John McKenna Technical Specialist	2	Consulting Scientist - cyanide code gap analysis audits (5), assay laboratory setup and audits, occupational hygiene survey, NATA auditor	Various gold and coal mining operations in Australia, Papua New Guinea and Tanzania
	14	Chief Scientist and Chief Chemist – occupational hygienist, cyanide code team leader, various process projects and research, assay laboratory management and accreditation, dangerous goods control, NATA auditor.	Porgera Gold Mine, Papua New Guinea
	5	Superintendent, Occupational Hygiene and Environmental Chemistry	Bougainville Copper Ltd., Papua New Guinea
	7	Associate Professor, Department of Chemical Technology	University of Technology, Papua New Guinea



Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than two consecutive Cyanide Code audits of this facility. I have participated in at least 3 health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed,	<u>Name</u>	<u>Signature</u>	<u>Date</u>
Lead Auditor*	Hugh Wyndham		12/03/2008
Auditor 1	John McKenna		12/03/2008

Use additional pages if necessary

*The lead auditor's signature must be certified by notarization or equivalent.


Signature of Declarant. 

Declared at: 124 Pacific Highway, Greenwich. NSW 2065 Australia


This: 12th day of March 2008

Before me: Kylie Jane Lloyd, Justice of the Peace in and for the State of NSW

Signature

 JP 178914

Ahafo Gold Mine


Signature of Lead Auditor

March 12 2008