



INTERNATIONAL CYANIDE MANAGEMENT INSTITUTE

Auditor Credentials Form

Facility Audited: Pueblo Viejo Mine, Dominican Republic

Date: October 13 to 17, 2014

Auditor and Technical Specialist Credentials:

Lead Auditor: Kent R. Johnjack
 Auditor Certification Number: Certified Environmental Auditor No. 35173
 Certifying Organization: National Registry of Environmental Professionals (NREP)
 Telephone Number: (847) 724-4223
 Address: P.O. Box 2099, Glenview, IL, United States of America
 Web Site Address: www.nrep.org
 Minimum Experience: 3 Audits in past 7 years as Lead Auditor

Year	Type of Facility, Type of Audit Led	Country
Mining – International Cyanide Management Code Pre-Signatory Services (Design Reviews)		
2013	Mining Technical Specialist for Rubicon Phoenix Mine	Ontario, Canada
Mining – International Cyanide Management Code Pre-Certification Audits (Gap Analyses)		
2009	Mining Technical Specialist for Peñoles La Herradura Mine	Sonora, Mexico
2011	Mining Technical Specialist for GoldCorp Wharf Mine	South Dakota, USA
2011	Lead Auditor and Mining Technical Specialist for GoldCorp Peñasquito Mine	Zacatecas, Mexico
2013	Lead Auditor and Mining Technical Specialist for GoldCorp Los Filos Mine	Guerrero, Mexico
2013	Lead Auditor and Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru
2014	Lead Auditor and Mining Technical Specialist for Newmont Emigrant Mine	Nevada, USA
Mining – International Cyanide Management Code Certification Audits (Initial or Recertification)		
2010	Mining Technical Specialist for Newmont Twin Creeks Mine	Nevada, USA
2010	Mining Technical Specialist for Barrick Lagunas Norte Mine	Santiago de Chuco, Peru
2011	Mining Technical Specialist for Peñoles La Herradura Mine	Sonora, Mexico
2011	Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru
2011	Lead Auditor and Mining Technical Specialist for Newmont Phoenix Mine	Nevada, USA
2012	Lead Auditor and Mining Technical Specialist for Newmont Carlin Mine	Nevada, USA
2012	Lead Auditor and Mining Technical Specialist for Goldcorp Peñasquito Mine	Zacatecas, Mexico
2012	Lead Auditor and Mining Technical Specialist for Goldcorp Wharf Mine	South Dakota, USA
2012	Lead Auditor and Mining Technical Specialist for Minas de Oro Mulatos Mine	Sonora, Mexico
2013	Lead Auditor and Mining Technical Specialist for Goldcorp Los Filos Mine	Guerrero, Mexico
2013	Lead Auditor and Mining Technical Specialist for Goldcorp Red Lake Gold Mines	Ontario, Canada
2014	Lead Auditor and Mining Technical Specialist for New Gold Cerro de San Pedro Mine	San Luis Potosi, Mexico
2014	Lead Auditor and Mining Technical Specialist for Peñoles La Herradura	Sonora, Mexico



**Pueblo Viejo Mine, Dominican Republic
Initial Certification Audit**

Year	Type of Facility, Type of Audit Led	Country
	Mine	
2014	Lead Auditor and Mining Technical Specialist for Newmont Yanacocha Mine	Cajamarca, Peru
2014	Lead Auditor and Mining Technical Specialist for Goldcorp El Sauzal Mine	Chihuahua, Mexico
Mining – Regulatory Compliance Audits		
2012	Lead Auditor for Regulatory Compliance Audit at Thompson Creek Mine	Idaho, USA
Due Diligence and Regulatory Assessments		
2005	Project Manager for Due Diligence Assessment of the ASARCO Ray Mine against Arizona Groundwater Regulations, Surface Water Regulations, and Best Available Demonstrated Control Technology (BADCT) Requirements	Arizona, USA
2008-2010	Lead Inspector for Monthly Stormwater Inspections for Compliance with Aquifer Protection Permit No. P-101703 at the West Plant Site of the Superior Mine	Arizona, USA
2011	Lead Inspector for Non-Stormwater Discharge Inspection of the Copper Basin Mine with respect to Arizona Multi-Sector General Permit requirements.	Arizona, USA
2012	Lead Assessor for Five-Year Inspection of Best Available Demonstrated Technology (BADCT) Requirements at Closed Facilities for Compliance with Aquifer Protection Permit No. P-101703 at the West Plant Site of the Superior Mine	Arizona, USA
2012	Inspector for petroleum facilities and oil-filled equipment at the Copper Queen Branch as part of updating the Spill Prevention, Control, and Countermeasure Plan	Arizona, USA

Cyanide-related Operations Experience

Each auditor must have at least 3 years; at least one auditor must have at least 7 years' experience.

Auditor	Yrs.	Relevant Position Titles	Types of Operations
Kent R. Johnejack	20+	Registered Professional Engineer (Civil); Senior Engineer/Principal; and Certified Environmental Auditor	Since 1995, Kent has worked in the mining industry as a consulting engineer and hydrologist. He has been involved with groundwater and surface water permitting, closure, remediation, spill cleanup, due diligence, waste characterization, sampling and analysis, civil design, construction oversight, regulatory compliance inspections, and auditing. Prior to 1995, Kent worked in land development, infrastructure, and low-level radioactive waste projects.
Ivon Aguinaga	14+	Senior Project Engineer	Since 2000, Ivon has worked in the mining industry as a consulting engineer with emphasis on environmental mine permitting, regulatory compliance auditing, surface water engineering, environmental impact assessments and baseline studies.



**Pueblo Viejo Mine, Dominican Republic
Initial Certification Audit**

Statement of No Conflict

I certify that I have not audited any component of this facility for which I was responsible for design or development; nor have I within the past year been an employee of the facility, its parent company, or associated affiliates. Excluding audits, I have not derived more than 30% of my income within the past 5 years from the facility, its parent, or associated affiliates. I have not participated in more than three consecutive Cyanide Code audits of this facility. I have participated in at least three health, safety, and/or environmental audits in the past 7 years and am familiar with standard audit procedures as well as with the protocols developed by the International Cyanide Management Institute for implementation of the Code.

Signed	Name	Signature	Date
Lead Auditor* and Mining Technical Specialist	Kent Johnejack	<i>Kent R. Johnejack</i>	December 19, 2014
Mining Technical Specialist	Ivon Aguinaga	<i>Ivon Aguinaga</i>	December 19, 2014


Use additional pages if necessary

*The lead auditor's signature must be certified by notarization or equivalent.

State of Arizona)
County of PIMA)
(Arizona County)

Subscribed and sworn (or affirmed) before me this 18th day December, 2014
[Day] [Month] [Year]

by Kent Johnejack
[Name of Signer]



Rosina Thorne
[Notary Signature]
Notary Public